



Sample

Inspection Date:

Prepared For:

Prepared By:

Advanced Home Inspection Service
725 Panama Ln. D-3, 229
Yuba City, Ca. 93313

661-858-4790
661-833-3888 Fax
ken@ahis.bus

Report Number:

Inspector:

TABLE OF CONTENTS

REPORT OVERVIEW	3
RECEIPT/INVOICE	4
GROUNDS	5
ROOF	6
EXTERIOR	7
ELECTRICAL/AC-HEAT PUMP	8
GARAGE	9
KITCHEN/LAUNDRY ROOM	10
BATHROOMS	12
ROOMS	15
INTERIOR	18
BASEMENT	19
CRAWL SPACE	20
PLUMBING	21
HEATING SYSTEM	22
ELECTRIC/COOLING SYSTEM	23
SUMMARY	24

REPORT OVERVIEW

THE HOUSE IN PERSPECTIVE

CONVENTIONS USED IN THIS REPORT

SATISFACTORY - Indicates the component is functionally consistent with its original purpose but may show signs of normal wear and tear and deterioration.

MARGINAL - Indicates the component will probably require repair or replacement anytime within five years.

POOR - Indicates the component will need repair or replacement now or in the year or near future.

MAJOR CONCERNS - A system or component that is considered significantly deficient and is unsafe.

SAFETY HAZARD - Denotes a condition that is unsafe and in need of prompt attention.

THE SCOPE OF THE INSPECTION

All components designated for inspection in the ASHI® Standards of Practice are inspected, except as may be noted in the “Limitations of Inspection” sections within this report.

It is the goal of the inspection to put a home buyer in a better position to make a buying decision. Not all improvements will be identified during this inspection. Unexpected repairs should still be anticipated. This inspection should not be considered a guarantee or warranty of any kind.

Please refer to the pre-inspection contract for an explanation of the scope of the inspection.

BUILDING DATA

Approximate Age: INFO
Street: INFO
Main Entrance Faces: INFO
Date of Occupancy: INFO
Residential Use: INFO
Refrigeration: INFO
Ground cover: INFO
How Paid: INFO

Sample

RECEIPT / INVOICE

Advanced Home Inspection Service
4725 Panama Ln. D-3, 229
Bakersfield, Ca. 93313
661-858-4790

Date: **2/13/2009**

Inspection Number: **0902167451**

Name: **Gerardo Martinez**

Inspection: 300.00
Other** _____
Total: _____

- Check #:
- Cash
- Credit Card:
- Escrow

- ** Radon Pool / Hot Tub Shipping Well & Septic WDO/WDI
- Duct pressure testing Mold sampling **

Inspected by: **Joseph Stotts Jr.**

Sample



SERVICE WALKS None *Public sidewalk needs repair*

Material: Concrete Flagstone Gravel Brick Other

Condition: Satisfactory Marginal Poor *Trip Hazard*

Pitched towards home *Settling cracks* Not visible Typical cracks

DRIVEWAY/PARKING None

Material: Concrete Asphalt Gravel/Dirt Brick Other

Condition: Satisfactory Marginal Poor Fill cracks and seal

Pitched towards home *Trip hazard* *Settling Cracks* *Crack*

PORCH (covered entrance) None

Support Pier: Concrete Wood Not visible Other

Condition: Satisfactory Marginal Poor *Railing/Balusters recommended*

Floor: Satisfactory Marginal Poor *Safety Hazard*

STOOPS/STEPS None *Uneven risers*

Material: Concrete Wood Other *Beiling/Balusters recommended*

Condition: Satisfactory Marginal Poor *Settled*

Rotted/Damaged *Safety Hazard*

PATIO None

Material: Concrete Flagstone Kool-Deck® Brick *Trip hazard*

Condition: Satisfactory Marginal Poor *Settling Cracks*

Pitched towards home (See remarks page) *Damage provided* Typical cracks

DECK/BALCONY (flat, floored, roofless area) None

Material: Wood Metal Composite Not visible *Railing/Balusters recommended*

Finish: Treated Painted/Stained Other

Improper attachment to house *Railing loose*

Condition: Satisfactory Marginal Poor *Wood in contact with soil*

DECK/PATIO/PORCH COVERS None *Earth to wood contact* *Moisture/Insect damage*

Condition: Satisfactory Marginal Poor *Posts/Supports need Repair*

Recommend: Metal Straps/Bolts/Flashing *Improper attachment to house*

FENCE/WALL Not evaluated None

Type: Block/Block Wood Metal Chain Link *Rusted* Other

Condition: Satisfactory Marginal Poor *Loose Blocks/Caps* Typical cracks

Gate: N/A Satisfactory Marginal Poor *Planks missing/damaged*

LANDSCAPING AFFECTING FOUNDATION (See remarks page)

Negative Grade: East West North South Satisfactory

Recommend additional backfill *Recommend window wells/covers* *Trim back trees/shrubberies*

Wood in contact with/in proper clearance to soil Yard drains observed - not tested

RETAINING WALL None **Material:** *Drainage holes recommended*

Condition: Satisfactory Marginal Poor *Safety Hazard* *Leaning/cracked/bowed*

(Relates to the visual condition of the wall)

HOSE BIBS None No anti-siphon valve

Operates: Yes No Not tested Not on

GENERAL COMMENTS

INFO



ROOF VISIBILITY All Partial None Limited by:

INSPECTED FROM Roof Ladder at eaves Ground (*Inspection Limited*) With Binoculars

STYLE OF ROOF

Type: Gable Hip Mansard Shed Flat Other
Pitch: Low Medium Steep Flat

ROOF COVERING

Roof #1: Type: **INFO** Estimated Layers: **INFO** Approximate age of cover: **INFO** years
Roof #2: Type: **INFO** Estimated Layers: **INFO** Approximate age of cover: **INFO** years
Roof #3: Type: **INFO** Estimated Layers: **INFO** Approximate age of cover: **INFO** years

VENTILATION SYSTEM **Type:** Soffit Ridge Gable Roof
Appears Adequate: Yes No Turbine Powered Other
(See Interior remarks page) (See Attic section)

FLASHING **Material:** Galv/Alum Asphalt Not visible Rubber Lead
 Copper Foam Other
Condition: Not visible Satisfactory Marginal Rusted
 Separated from chimney/roof Recommend Sealing Other

VALLEYS N/A **Material:** Galv/Alum Asphalt Lead Copper
 Not visible Other
Condition: Not visible Satisfactory Marginal Poor
 Rusted Holes Recommend Sealing

CONDITION OF ROOF COVERINGS **Roof #1:** Satisfactory Marginal Poor
Roof #2: Satisfactory Marginal Poor
Roof #3: Satisfactory Marginal Poor
Condition: Curling Cracking Ponding Burn Spots Broken/Loose Tiles/Shingles
 Nail popping Granule missing Alligatoring Blistering Missing Tabs/Shingles/Tiles
 Moss buildup Exposed rafters Cupping Incomplete/Improper Nailing

SKYLIGHTS N/A Cracked/Broken Not visible
Condition: Satisfactory Marginal Poor

PLUMBING VENTS Yes No Satisfactory Marginal Poor
 Recommend roofer evaluate Not Visible

Conditions reported above reflect visible portion only

GENERAL COMMENTS

INFO



EXTERIOR

CHIMNEY(S) None Location(s): **INFO**

Viewed From: Roof Ladder at eaves Ground with binoculars

Rain Cap/Spark Arrestor: Yes No **Recommended**

Chase: Brick Stone Metal Blocks Framed

Evidence of: Holes in metal Cracked chimney cap Loose mortar joints Flaking Loose Brick Rust

Flue: Tile Metal **Unlined** Not visible

Evidence of: Scaling Cracks Creosote **Not evaluated (See remarks page)**

Have flue(s) cleaned and re-evaluated **Recommend Cricket/Saddle/Flashing**

Condition: Satisfactory Marginal Poor

GUTTERS/SCUPPERS/EAVESTROUGH None **Needs to be cleaned** **Downspout needed**

Material: Copper Vinyl/Plastic Galvanized/Aluminum Other

Condition: Satisfactory Marginal Poor **Recommend repair/painting**

Leaking: Corners Joints **Hole in main run**

Attachment: Loose **Missing spikes** **Improperly sloped (See remarks page)**

Extension needed: North South East West

SIDING None **See remarks page EIFS)**

Material: Stone Slate Block/Brick Fiberboard Fiber-cement Stucco

EIFS* Asphalt Wood Metal/Steel Other

Typical cracks **Monitor** **Wood rot** Peeling paint **Loose/Missing/Holes**

Condition: Satisfactory Marginal Poor **Recommend repair/painting**

TRIM, SOFFIT, FASCIA, FLASHING

Material: Wood Fiberboard Aluminum/Steel Fiber Cement Stucco

Recommend repair/painting **Damaged wood** Other

Condition: Satisfactory Marginal Poor

CAULKING

Condition: Satisfactory Marginal Poor

Recommend repair/painting windows/doors/masonry ledges/corners/utility penetrations

WINDOWS & SCREENS None **Cracked/fogged insulated glass**

Material: Wood Metal/Steel Vinyl Aluminum/Vinyl Clad

Screens: None Bent Not installed Glazing/caulk needed

Condition: Satisfactory Marginal Poor **Wood rot** **Recommend repair/painting**

STORMS WINDOWS None Not installed Wood Clad comb. Wood/metal comb.

Putty: Satisfactory **Glazing/caulk needed** N/A

Condition: Satisfactory **Broken/cracked** **Wood rot** **Recommend repair/painting**

SLAB-ON-GRADE/FOUNDATION N/A (See Basement/Crawl Space)

Stem Wall: Concrete block Poured concrete Other

Condition: Satisfactory Marginal Poor Not visible

Slab: Post tensioned Poured concrete Other

Condition: Satisfactory Marginal Poor **(See comments page)**

GENERAL COMMENTS

INFO



ELECTRICAL/A/C - HEAT PUMP

SERVICE ENTRY

- Underground Overhead *Weather head/mast needs repair* Condition: Sat. Marginal Poor
Exterior outlets: Yes No **Operative:** Yes No *Overhead wires too low*
GFCI present: Yes No **Operative:** Yes No *Less than 3' from balcony/deck/windows*
 Reverse polarity Open ground Safety Hazard

BUILDING(S) EXTERIOR WALL CONSTRUCTION

- Type:** Not visible Framed Masonry Other
Condition: Satisfactory Marginal Poor Not visible

EXTERIOR DOORS

- | | | | | |
|--------------------------|---------------------------------------|-----------------------------------|-------------------------------|----------------------------------|
| | | Patio | Storm | Other |
| Weatherstripping: | <input type="checkbox"/> Satisfactory | <input type="checkbox"/> Marginal | <input type="checkbox"/> Poor | <input type="checkbox"/> Missing |
| Door Condition: | <input type="checkbox"/> Satisfactory | <input type="checkbox"/> Marginal | <input type="checkbox"/> Poor | <input type="checkbox"/> Replace |

EXTERIOR A/C - HEAT PUMP

- UNIT #1:** N/A **Location:** _____
 Brand: **INFO** Model #: **INFO** Approximate age: **INFO** yrs.
Outside Disconnect: Yes No Maximum fuse/breaker rating: ??? Amp Fuses/breakers installed: ??? Amp
Level: Yes No Cabinet/housing rusted Improperly sized fuses/breakers
Condenser Fins: Damaged Need cleaning Damaged base/pad
Condition: Satisfactory Marginal Poor

- UNIT #2:** N/A **Location:** _____
 Brand: **INFO** Model #: **INFO** Approximate age: **INFO** yrs.
Outside Disconnect: Yes No Maximum fuse/breaker rating: ??? Amp Fuses/breakers installed: ??? Amp
Level: Yes No Cabinet/housing rusted Improperly sized fuses/breakers
Condenser Fins: Damaged Need cleaning Damaged base/pad
Condition: Satisfactory Marginal Poor

GENERAL COMMENTS

INFO



GARAGE

TYPE None
 Attached Detached 1-car 2-car 3-car 4-car

AUTOMATIC OPENER
 Yes No Operable Inoperable *Remote not available*

SAFETY REVERSE
Operable: Pressure reverse Electric eye *Need(s) adjusting* *Safety hazard*

ROOFING
Material: Same as house Type: **INFO** Approx. Age: **INFO** Approx. layers: **INFO**

GUTTERS / EAVESTROUGH
Condition: Satisfactory None Marginal Poor

SIDING / TRIM
Siding: Same as house Wood Masonry Metal Vinyl
 Stucco Masonry Slate Fiberboard
Trim: Same as house Wood Aluminum Vinyl

FLOOR
Material: Concrete Gravel Asphalt Dirt Other
Condition: Satisfactory Typical cracks *Settling cracks* *Recommend evaluation/repair*
Burners less than 18" above garage floor: N/A Yes No *Safety hazard*

SILL PLATES
 Not visible Floor level Elevated *Rotted/Damaged* *Recommend repair*

OVERHEAD DOOR(S)
Material: N/A Wood Fiberglass Masonite Metal *Recommend repair*
Condition: Satisfactory Marginal Poor *Overhead door hardware loose*
Recommend Priming/Painting Inside & Outside Yes No *Recommend lubrication* *Weather-stripping missing/damaged*

EXTERIOR SERVICE DOOR
Condition: Satisfactory Marginal Poor *Damaged/Rusted*

ELECTRICITY PRESENT
Reverse Polarity: Yes No Not visible *Safety hazard*
GFCI Present: Yes No Operates: Yes No *Handyman/extension cord wiring*

FIRE SEPARATION WALLS & CEILING *(Between garage & living area)*
Condition: N/A Present *Missing*
 Satisfactory *Safety hazard(s)* *Recommend repair* *Holes walls/ceiling*
Fire door: Non-verifiable *Not a fire door* *Needs repair* Satisfactory
 N/A Satisfactory Inoperative Missing *Needs repair*
Moisture Stains Present: Yes No Typical Cracks: Yes No

GENERAL COMMENTS
INFO



COUNTERTOPS

Grouting Joints:

- Satisfactory
- Marginal
- Recommend repair/caulking*
- Recommend sealing all tile grouting joints.

CABINETS

- Satisfactory
- Marginal
- Recommend repair/adjustment*

PLUMBING COMMENTS

- Faucet Leaks:** Yes No
- Sink/Faucet:** Satisfactory Corroded Chipped Cracked *Recommend repair*
- Functional Drainage:** Adequate Poor
- Functional Flow:** Adequate Poor
- Pipes leak/corroded:** Yes No

WALLS & CEILING

- Condition:** Satisfactory Marginal Poor
- Type cracks Moisture stains

HEATING / COOLING SOURCE

- Yes
- No

FLOOR

- Condition:** Satisfactory Marginal Poor
- Squeaks

APPLIANCES

(See remarks page)

- Disposal *Operates:* Yes No
- Oven *Operates:* Yes No
- Range *Operates:* Yes No
- Dishwasher *Operates:* Yes No
- Other *Operates:* Yes No
- Trash compactor *Operates:* Yes No
- Exhaust fan *Operates:* Yes No
- Refrigerator *Operates:* Yes No
- Freezer *Operates:* Yes No
- Dishwasher Air gap:** Yes No
- Dishwasher Drain Line Loaded:** Yes No
- Outlets Present:** Yes No
- Outlet GFI:** Yes No
- G.F.C.I.:** Yes No
- Open ground/Reverse polarity within 6' of:** Yes No *Potential safety hazard(s)*

GENERAL COMMENTS

INFO

Sample

LAUNDRY ROOM

ROOM COMPONENTS

Laundry sink: N/A **Faucet leaks:** Yes No **Pipes leak:** Yes No
Cross connections: Yes No **Heat source present:** Yes No **Room vented:** Yes No
Dryer vented: N/A Wall Ceiling Floor Not vented
 Not vented to Exterior *Recommend repair* *Safety hazard*
Electrical: Open ground/reverse polarity within 6' of water: Yes No *Safety hazard*
G.F.C.I. present: Yes No **Operates:** Yes No
Appliances: Washer Dryer Water heater Furnace
Washer hook-up lines/valves: Leaking Corroded Not visible
Gas Shut-off Valve: N/A Yes No Cap Needed *Safety hazard* Not visible

GENERAL COMMENTS

INFO

Sample

BATHROOM(S)

BATH: **INFO**

SINKS / TUBS / SHOWERS

Faucet leaks: Yes No Loose: Yes No Pipes leak: Yes No
Fixture(s) Condition: Satisfactory Marginal Poor

TOILET

Bowl Loose: Yes No Operates: Yes No Toilet leaks Cracked bowl/tank Cross connection

SHOWER / TUB AREA / SINK(S)

Material: Ceramic/Plastic Fiberglass Masonite Other
Condition: Satisfactory Marginal Poor Dented floors
Caulk/Grouting Needed: Yes No Where: Adequate Poor
Functional Drainage: Adequate Poor Functional Flow: Poor
Grouting Joints: Recommend sealing all tile grouting joints.
Whirlpool Operable: N/A Yes No Access panel to pump/motor: Yes No

WALLS / CEILING / CABINETS

Moisture stains present: Yes No Outlets present: Yes No
G.F.C.I. Present: Yes No Operates: Yes No
Open ground/Reverse polarity within 6' of water: Yes No Potential safety hazards present: Yes No

HEATING / COOLING SOURCE

Window/Door: Yes No Satisfactory Marginal Poor
Exhaust Fan: Yes No Operates: Yes No No Yes No

GENERAL COMMENTS

INFO

Sample

BATHROOM(S)

BATH: **INFO**

SINKS / TUBS / SHOWERS

Faucet leaks: Yes No Loose: Yes No Pipes leak: Yes No
Fixture(s) Condition: Satisfactory Marginal Poor

TOILET

Bowl Loose: Yes No Operates: Yes No Toilet leaks: Yes No Cracked bowl: Yes No Cross connection: Yes No

SHOWER / TUB AREA / SINK(S)

Material: Ceramic/Plastic Fiberglass Masonry Other
Condition: Satisfactory Marginal Poor Rotted floor: Yes No
Caulk/Grouting Needed: Yes No Where: Yes No
Functional Drainage: Adequate Poor Functional Flow: Adequate Poor
Grouting Joints: Recommend sealing all tile grouting joints.
Whirlpool Operable: N/A Yes No Access panel: Yes No Pump/motor: Yes No

WALLS / CEILING / CABINETS

Moisture stains present: Yes No Odors present: Yes No
G.F.C.I. present: Yes No Operable: Yes No
Open ground/Reverse polarity within 6' of water: Yes No Potential electrical hazards present: Yes No

HEAT / COOLING SOURCE

Window/Door: Yes No Satisfactory Marginal Poor
Exhaust Fan: Yes No Operable: Yes No Noisy: Yes No

GENERAL COMMENTS

INFO

Sample

 **BATHROOM(S)**

BATH: **INFO**

SINKS / TUBS / SHOWERS

Faucet leaks: Yes No **Loose:** Yes No **Pipes leak:** Yes No
Fixture(s) Condition: Satisfactory Marginal Poor

TOILET

Bowl Loose: Yes No **Operates:** Yes No Toilet leaks Cracked bowl/tank Cross connection

SHOWER / TUB AREA / SINK(S)

Material: Ceramic/Plastic Fiberglass Masonite Other
Condition: Satisfactory Marginal Poor Dotted floors
Caulk/Grouting Needed: Yes No **Where:** Shower Tub Sink
Functional Drainage: Adequate Poor **Function Flow:** Good Poor
Grouting Joints: Recommend sealing all tile grouting joints.
Whirlpool Operable: N/A Yes No **Access panel to pump/motor:** Yes No

WALLS / CEILING / CABINETS

Moisture stains present: Yes No **Outlets present:** Yes No
G.F.C.I. present: Yes No **Operates:** Yes No
Open ground/Reverse polarity within 6' of water: Yes No **Potential safety hazards present:** Yes No

GENERAL COMMENTS

INFO

Sample



LOCATION: INFO INFO

Walls & Ceiling: Satisfactory Marginal Poor
Moisture stains: Yes No Where: Squeaks Slopes
Floor: Satisfactory Marginal Poor
Typical cracks: Yes No
Ceiling Fan: N/A Satisfactory Marginal Poor
Electrical: **Switches:** Yes No **Outlets:** Yes No **Operates:** Yes No
Open ground/Reverse polarity: Yes No Cover plates missing Safety Hazard
Heating/Cooling Source: Yes No **Holes:** Doors Walls Ceilings
Bedroom Egress Restricted: N/A Yes No
Doors & Windows: Operational: Yes No
Locks/Latches Operable: Yes No Missing Cracked Glass

GENERAL COMMENTS

INFO

LOCATION: INFO INFO

Walls & Ceiling: Satisfactory Marginal Poor
Moisture stains: Yes No Where: Squeaks Slopes
Floor: Satisfactory Marginal Poor
Typical cracks: Yes No
Ceiling Fan: N/A Satisfactory Marginal Poor
Electrical: **Switches:** Yes No **Outlets:** Yes No **Operates:** Yes No
Open ground/Reverse polarity: Yes No Cover plates missing Safety Hazard
Heating/Cooling Source: Yes No **Holes:** Doors Walls Ceilings
Bedroom Egress Restricted: N/A Yes No
Doors & Windows: Operational: Yes No
Locks/Latches Operable: Yes No Missing Cracked Glass

GENERAL COMMENTS

INFO

LOCATION: INFO INFO

Walls & Ceiling: Satisfactory Marginal Poor
Moisture stains: Yes No Where: Squeaks Slopes
Floor: Satisfactory Marginal Poor
Typical cracks: Yes No
Ceiling Fan: N/A Satisfactory Marginal Poor
Electrical: **Switches:** Yes No **Outlets:** Yes No **Operates:** Yes No
Open ground/Reverse polarity: Yes No Cover plates missing Safety Hazard
Heating/Cooling Source: Yes No **Holes:** Doors Walls Ceilings
Bedroom Egress Restricted: N/A Yes No
Doors & Windows: Operational: Yes No
Locks/Latches Operable: Yes No Missing Cracked Glass

GENERAL COMMENTS

INFO



LOCATION: INFO INFO

Walls & Ceiling: Satisfactory Marginal Poor
 Moisture stains: Yes No Where: Squeaks Slopes
 Floor: Satisfactory Marginal Poor
 Typical cracks: Yes No
 Ceiling Fan: N/A Satisfactory Marginal Poor
 Electrical: Switches: Yes No Outlets: Yes No Operates: Yes No
 Open ground/Reverse polarity: Yes No Cover plates missing Safety Hazard
 Heating/Cooling Source: Yes No Holes: Doors Walls Ceilings
 Bedroom Egress Restricted: N/A Yes No
 Doors & Windows: Operational: Yes No
 Locks/Latches Operable: Yes No Missing Cracked Glass

GENERAL COMMENTS

INFO

LOCATION: INFO INFO

Walls & Ceiling: Satisfactory Marginal Poor
 Moisture stains: Yes No Where: Squeaks Slopes
 Floor: Satisfactory Marginal Poor
 Typical cracks: Yes No
 Ceiling Fan: N/A Satisfactory Marginal Poor
 Electrical: Switches: Yes No Outlets: Yes No Operates: Yes No
 Open ground/Reverse polarity: Yes No Cover plates missing Safety Hazard
 Heating/Cooling Source: Yes No Holes: Doors Walls Ceilings
 Bedroom Egress Restricted: N/A Yes No
 Doors & Windows: Operational: Yes No
 Locks/Latches Operable: Yes No Missing Cracked Glass

GENERAL COMMENTS

INFO

LOCATION: INFO INFO

Walls & Ceiling: Satisfactory Marginal Poor
 Moisture stains: Yes No Where: Squeaks Slopes
 Floor: Satisfactory Marginal Poor
 Typical cracks: Yes No
 Ceiling Fan: N/A Satisfactory Marginal Poor
 Electrical: Switches: Yes No Outlets: Yes No Operates: Yes No
 Open ground/Reverse polarity: Yes No Cover plates missing Safety Hazard
 Heating/Cooling Source: Yes No Holes: Doors Walls Ceilings
 Bedroom Egress Restricted: N/A Yes No
 Doors & Windows: Operational: Yes No
 Locks/Latches Operable: Yes No Missing Cracked Glass

GENERAL COMMENTS

INFO



LOCATION: INFO INFO

Walls & Ceiling: Satisfactory Marginal Poor
 Moisture stains: Yes No Where: Squeaks Slopes
 Floor: Satisfactory Marginal Poor
 Typical cracks: Yes No
 Ceiling Fan: N/A Satisfactory Marginal Poor
 Electrical: Switches: Yes No Outlets: Yes No Operates: Yes No
 Open ground/Reverse polarity: Yes No Cover plates missing Safety Hazard
 Heating/Cooling Source: Yes No Holes: Doors Walls Ceilings
 Bedroom Egress Restricted: N/A Yes No
 Doors & Windows: Operational: Yes No
 Locks/Latches Operable: Yes No Missing Cracked Glass

GENERAL COMMENTS

INFO

LOCATION: INFO INFO

Walls & Ceiling: Satisfactory Marginal Poor
 Moisture stains: Yes No Where: Squeaks Slopes
 Floor: Satisfactory Marginal Poor
 Typical cracks: Yes No
 Ceiling Fan: N/A Satisfactory Marginal Poor
 Electrical: Switches: Yes No Outlets: Yes No Operates: Yes No
 Open ground/Reverse polarity: Yes No Cover plates missing Safety Hazard
 Heating/Cooling Source: Yes No Holes: Doors Walls Ceilings
 Bedroom Egress Restricted: N/A Yes No
 Doors & Windows: Operational: Yes No
 Locks/Latches Operable: Yes No Missing Cracked Glass

GENERAL COMMENTS

INFO

LOCATION: INFO INFO

Walls & Ceiling: Satisfactory Marginal Poor
 Moisture stains: Yes No Where: Squeaks Slopes
 Floor: Satisfactory Marginal Poor
 Typical cracks: Yes No
 Ceiling Fan: N/A Satisfactory Marginal Poor
 Electrical: Switches: Yes No Outlets: Yes No Operates: Yes No
 Open ground/Reverse polarity: Yes No Cover plates missing Safety Hazard
 Heating/Cooling Source: Yes No Holes: Doors Walls Ceilings
 Bedroom Egress Restricted: N/A Yes No
 Doors & Windows: Operational: Yes No
 Locks/Latches Operable: Yes No Missing Cracked Glass

GENERAL COMMENTS

INFO



INTERIOR WINDOWS / GLASS

Condition: Satisfactory Marginal Poor Needs repair
 Representative number of windows operated Painted shut (See remarks page)
Evidence of Leaking Insulated Glass: Yes No N/A **Safety Glazing Needed:** Yes No
 Glazing compound needed Cracked glass Hardware missing Broken counter-balance mechanism
Security Bars Present: Yes No Not tested Safety hazard Test release mechanism before moving in

FIREPLACE

None Location(s): **INFO**
Type: Gas (Not Tested) Wood Wood burner stove (See remarks page) Electric Ventless
Material: Masonry Metal (pre-fabricated) Metal insert
Miscellaneous: Blower built-in Operates: Yes No Damper operates: Yes No
 Open joints or cracks in firebrick/panels should be sealed Fireplace door needs repair
Damper Modified for Gas Operation: Yes No Damper missing Pre-fab panel damaged/worn
Hearth Adequate: Yes No **Mantle:** N/A Satisfactory Adequate Loose/missing
Physical Condition: Satisfactory Marginal Poor Recommend having cleaned and re-examined

STAIRS / STEPS / BALCONIES

Satisfactory Marginal Poor None
Handrail: Satisfactory Marginal Poor Safety hazard
Risers/Treads: Satisfactory Marginal Poor Risers/Treads uneven

SMOKE / CARBON MONOXIDE DETECTORS

(See remarks page)
Present: Smoke Detector: Yes No Not tested **Operational:** Yes No Not tested
 CO Detector: Yes No Not tested **Operational:** Yes No Not tested

ATTIC/STRUCTURE/FRAMING/INSULATION

N/A
Access: Stairs Pull down Attic hatch/Hatch No access Other
Inspected From: Access panel In the attic Other
Location: Bedroom hall Bedroom closet Garage Other
Access Limited By:
Flooring: Complete Partial None
Insulation: Type: **INFO** Batts Loose Average inches: **INFO**
 Damaged Missing Compressed Recommend Baffles @ Eaves
Installed In: Rafters Walls Between ceiling joists Not visible
 Recommend additional insulation
Ventilation: Ventilation appears adequate Recommend additional ventilation
Fans Exhausted To: N/A Attic Outside: Yes No Not visible
HVAC Duct: Satisfactory Leaking Split Disconnected Leaking Repair/Replace
Chimney: Satisfactory Needs repair Not visible
Structural Items Observed: Yes No Recommend repair Recommend Structural Engineer
Roof Structure: Rafters Trusses Wood Metal Other
Collar Ties Present: Yes No N/A
Roof Sheathing: Plywood OSB 1x Wood Rotted Stained Delaminated
Evidence of Condensation/Moisture Leaking: Yes No (See remarks page)
Ceiling Joists: Wood Metal Other Not visible
Vapor Barriers: Kraft/foil faced Plastic Not visible Improperly installed
Firewall Between Units: N/A Yes No Needs repair/sealing (See remarks page)
Electrical: Open junction box (es) Handyman wiring Visible knob-and-tube

GENERAL COMMENTS

INFO



BASEMENT

STAIRS N/A

- Condition:** Satisfactory Marginal Poor Typical wear and tear Need repair
Handrail: Yes No **Condition:** Satisfactory Loose
Headway Over Stairs: Satisfactory *Low clearance* *Safety hazard*

FOUNDATION **Condition:** Satisfactory Marginal *Have evaluated* *Monitor* *Monitor*


- Material:** Brick Concrete block Fieldstone Poured concrete
Horizontal Cracks: North South East West
Step Cracks: North South East West
Vertical Cracks: North South East West
Covered Walls: North South East West
Movement Apparent: North South East West
Indication Of Moisture: Yes No Fresh Old stains

Condition reported above reflects visible portion only

BASEMENT/CRAWL SPACE WALLS

Diagram indicates where wall not visible and type of covering:

- P = Paneling C = Crack(s)
 D = Drywall M = Monitor
 S = Storage E = Evaluate
 O = Other



- FLOOR **Material:**** Concrete Dist./Gravel Not visible Other
Condition: Satisfactory Marginal Poor Typical cracks

SEISMIC BOLTS

- N/A None visible Appear satisfactory Recommend evaluation

BASEMENT DRAINAGE

- Sump Pump:** Yes No Not working Not working Needs cleaning *Not tested*
Floor Drains: Yes Not visible **Tested:** Yes No Efflorescence present

GIRDERS / BEAMS / COLUMNS

- Material:** Steel Wood Block Concrete
 Not visible
Condition: Satisfactory Marginal Poor Stained/rusted

JOISTS

- Material:** Wood Steel Truss Not visible
 2x8 2x10 2x12 Engineered I-Type *Sagging/altered joists*
Condition: Satisfactory Marginal Poor

SUB FLOOR

- Indication of moisture stains/rotting
 ** Areas around shower stalls, etc., as viewed from basement or crawl space

GENERAL COMMENTS

INFO

CRAWL SPACE

CRAWL SPACE N/A Full crawlspace Combination basement/crawl space/slab
Conditioned (heated/cooled): Yes No

ACCESS Exterior Interior hatch door Via basement No Access
Inspected from: Access panel In the crawl space

FOUNDATION WALLS **Condition:** Satisfactory Marginal *Have evaluated* *Monitor*
 Concrete block Poured Stone
 Wood Brick Piers & columns
 Cracks Movement

FLOOR Concrete Gravel Dirt Other
 Typical cracks

SEISMIC BOLTS N/A None visible Apparently satisfactory Recommend evaluation

DRAINAGE Outside drain Sump pump: Yes No Operable: Yes No
 None apparent **Evidence of moisture damage:** Yes No

VENTILATION Wall vents Power vents None apparent

GIRDERS / BEAMS / COLUMNS Steel Wood Masonry Not visible
Condition: Satisfactory Marginal Poor

JOISTS **Material:** Wood Steel Truss Not visible
 2x8 2x10 2x12 Engineered I-Type *Sagging/altered joists*
Condition: Satisfactory Marginal Poor


SUB FLOOR Not visible Wood Concrete Other

MOISTURE STAINS None Walls Sub floor Other

INSULATION None Walls Between floor joists Other
Location: Walls

VAPOR BARRIER Yes No Other Not visible
 Kraft/felt face Plastic

BASEMENT/CRAWL SPACE WALLS
Diagram indicates where wall not visible and type of covering:
P = Paneling C = Crack(s)
D = Dry wall M = Monitor
S = Storage E = Evaluate
O = Other



GENERAL COMMENTS

INFO



WATER SERVICE

Main Shut-off Location: **INFO**

- Water Entry Piping:** Not visible Copper/Galv. Plastic* (PVC, CPVC, Polybutylene, PEX) Unknown
- Visible Water Distribution Piping:** Copper Galvanized Plastic* (PVC, CPVC, Polybutylene, PEX) Unknown
- Condition:** Satisfactory Marginal Poor
- Lead Other Than Solder Joints:** Yes No Unknown Service entry
- Functional Flow:** Adequate Poor Water pressure over 80 psi
- Pipes, Supply/Drain:** Corroded Leaking Valves broken/missing Dissimilar metal
- Drain/Waste/Vent Pipe:** Copper Cast iron Galvanized PVC AP
- Condition:** Satisfactory Marginal Poor **Cross connection:** Yes No
- Support/Insulation:** Type: **INFO**
- Traps Proper P-Type:** N/A Yes No Traps recommended
- Functional Drainage:** Adequate Poor Recommend plumbing evaluate
- Interior Fuel Storage System:** Yes No Leaking: Yes No
- Gas Line:** Copper Brass Black iron Stainless steel CSST Not visible
- Condition:** Satisfactory Marginal Poor

MAIN FUEL SHUT-OFF LOCATION **INFO**

WELL PUMP

- N/A Submersible N/A
- Location:** In basement Well house Well pit Shared well
- Pressure Gauge Operates:** Yes No Unknown Well pressure: ??? psi Not visible

SANITARY / GRINDER PUMP

- N/A
- Sealed Crock:** Yes No **Check Valve:** Yes No **Vented:** Yes No

WATER HEATER #1 N/A

- Brand name:** **INFO** **Condition:** Satisfactory Marginal Poor
- Type:** Gas Electric Oil Other
- Unit Elevated:** Yes No N/A Tank/Piping corroded/leaking
- Capacity:** **INFO** gallons **Approximate age:** **INFO** year(s)
- Combustion Air Venting Present:** Yes No N/A **Seismic restraints needed:** Yes No N/A
- Relief Valve:** Yes No Missing Recommend repair
- Vent Pipe:** N/A Satisfactory Pitch proper Improper Rusted Recommend repair

WATER HEATER #2 N/A

- Brand name:** **INFO** **Condition:** Satisfactory Marginal Poor
- Type:** Gas Electric Oil Other
- Unit Elevated:** Yes No N/A Tank/Piping corroded/leaking
- Capacity:** **INFO** gallons **Approximate age:** **INFO** year(s)
- Combustion Air Venting Present:** Yes No N/A **Seismic restraints needed:** Yes No N/A
- Relief Valve:** Yes No Missing Recommend repair
- Vent Pipe:** N/A Satisfactory Pitch proper Improper Rusted Recommend repair

WATER SOFTENER

(Unit not evaluated) N/A

- Loop Installed:** Yes No **Plumbing Hooked Up:** Yes No
- Softener Present:** Yes No **Plumbing Leaking:** Yes No

GENERAL COMMENTS

INFO



HEATING SYSTEM - UNIT #1 Location: **INFO** BTU's Model #: ??? (See remarks page)

Brand Name: **INFO** Approximate age: **INFO** year(s) Unknown

Energy Source: Gas LP Oil Electric Solid Fuel

Warm Air System: Belt drive Direct drive Gravity Central system Floor/Wall unit

Heat Exchanger: N/A (sealed) Visual w/mirror *Flame distortion* *Rusted* *Carbon/soot buildup*

Carbon Monoxide: N/A Detected at Plenum/Register Not tested

CO Test: Tester: **INFO** **Combustion Air Venting Present:** Yes No N/A

Controls: Disconnect: Yes No Normal operating and safety controls observed

Distribution: Metal duct Insul. flex duct Cold air returns Duct board *Asbestos-like wrap*

Flue Piping: N/A Rusted Improper slope *Safety hazard*

Supports for Piping/Insulation: N/A Yes No

Filter: Standard Electrostatic Satisfactory Needs cleaning/replacement Missing

When Turned On By Thermostat: Fired Did not fire Proper Operation: Yes No Not tested

Heat Pump: Aux. electric Aux. gas N/A **Sub-Slab ducts:** No N/A

System Not Operated Due To: Exterior temperature Other

Recommend technician examine **System Condition:** Satisfactory Marginal Poor

BOILER SYSTEM N/A

Brand Name: **INFO** Approximate age: **INFO** year(s) Unknown

Model #: ??? Serial #: ???

System not operated due to: **INFO**

Energy Source: Gas Oil Electric

Distribution: Hot water Baseboard Convector Radiator

Circulator: Pump Gravity Multiple zones

Controls: Temp/pressure gauge exists: Yes No **Operating:** Yes No

Oil Fired Units: Disconnect: Yes No **Combustion Air Venting Present:** Yes No N/A

Relief valve: Yes No Missing Extension proper: Yes No

Operated: **When turned on by thermostat:** Fired Did not fire

Operation: Satisfactory: Yes No *Recommend HVAC technician examine* *Before closing*

OTHER SYSTEMS N/A Electric baseboard Radiant ceiling cable


Gas space heater Wood burning stove (See Remarks page)

Proper Operation: Yes No

System Condition: Satisfactory Marginal Poor

GENERAL COMMENTS

INFO





ELECTRIC/COOLING SYSTEM

MAIN PANEL Location: **INFO** Condition: Satisfactory Marginal Poor
Adequate Clearance To Panel: Yes No Amperage: **INFO** Volts 120/240 Breakers Fuses
Appears Grounded: Yes No Not visible
G.F.C.I. present: Yes No **Operative:** Yes No
A.F.C.I. present: Yes No **Operative:** Yes No
MAIN WIRE: Copper Aluminum Copper clad aluminum Not visible
 Tapping before the main breaker *Double tapping of the main wire*
Condition: Satisfactory Poor *Federal Pacific Panel Stab Lock (See remarks page)**
BRANCH WIRE: Copper **Aluminum*** Copper clad aluminum Not visible
Condition: Satisfactory Poor *Recommend electrician evaluate/repair**
 Romex BX cable Conduit *Knob & tube***
 Double tapping *Wires undersized/oversized breaker/fuses*
 Panel not accessible Not evaluated **Reason:** **INFO**

SUB PANEL(S) None apparent
Location 1: **INFO** Location 2: **INFO** Location 3: **INFO**
 Panel not accessible Not evaluated **Reason:** **INFO**
Branch Wire: Copper Aluminum Copper clad aluminum
Neutral/ground separated: Yes No Neutral isolated: Yes No *Safety hazard*
Condition: Satisfactory Marginal Poor *Recommend separating/isolating neutrals*

ELECTRICAL FIXTURES

A representative number of installed lighting fixtures, switches, and receptacles located inside the house, garage, and exterior walls were tested and found to be:

Condition: Satisfactory Marginal Poor
 Open grounds Reverse polarity GFCIs not operating
 Solid conductor aluminum branch wiring circuits (See remarks page)*
 Ungrounded 3-prong outlets *Recommend electrician evaluate/repair**

GENERAL COMMENTS

INFO

COOLING SYSTEM - UNIT #1

Central system Wall Unit Location: **INFO** Age: **INFO** yrs.
Energy Source: Electric Gas Water Other
Unit Type: Air cooled Water cooled Gas chiller Geothermal Heat pump
Evaporator Coil: Satisfactory Not visible Needs cleaning Damaged
Refrigerant: *Leak* *Damage* *Insulation missing* Satisfactory
Condensate Line/Drain: To exterior To pump Floor drain Other
Operation: SAT:??? RTAT:??? Differential??? °F
Difference in temperature (split) should be 14-22° Fahrenheit (See remarks page)
Condition: Satisfactory Marginal Poor
 Not operated due to exterior temperature *Recommend HVAC technician examine/clean/service*

GENERAL COMMENTS

INFO



ITEMS NOT OPERATING

INFO

MAJOR CONCERNS

Item(s) that have failed or have potential of failing soon.

INFO

POTENTIAL SAFETY HAZARDS

INFO

DEFERRED COST ITEMS

INFO

-
- Items listed in this report may inadvertently have been left off the Summary Sheet.
 - Customer should read the entire report, including the Remarks.

Sample



REMARKS

SERVICE WALKS/DRIVEWAYS

Spalling concrete cannot be patched with concrete because the new will not bond with the old. Water will freeze between the two layers, or the concrete will break up from movement or wear. Replacement of the damaged section is recommended. Walks or driveways that are close to the property should be properly pitched away to direct water away from the foundation. Asphalt driveways should be kept sealed and larger cracks filled so as to prevent damage from frost.

Patios that have settled towards the structure should be mud jacked or replaced to assure proper pitch. Improperly pitched patios are one source of wet basements.

EXTERIOR WOOD SURFACES

All surfaces of untreated wood need regular applications of paint or special chemicals to resist damage. Porch or deck columns and fence posts, which are buried in the ground and made of untreated wood, will become damaged within a year or two.

Decks should always be nailed with galvanized, stainless steel or aluminum nails. Decks that are not painted or stained should be treated with a water sealer.

GRADING AND DRAINAGE

Any system of grading or landscaping that creates positive drainage (moving water away from the foundation walls) will help to keep a basement dry. Where negative grade exists and additional backfill is suggested, it may require digging out around the property to get a proper pitch. Dirt shall be approximately 6" below the bottom sill and should not touch wood surfaces.

Flower beds, loose mulched areas, railroad ties and other such landscaping items close to the foundation trap moisture and contribute to wet basements. To establish a positive grade, a proper slope away from the house is 1" per foot for approximately 5-6 feet. Recommend ground cover planting or grass up to foundation.

ROOF AND SURFACE WATER CONTROL

Roof and surface water must be controlled to maintain a dry basement. This means keeping gutters cleaned out and aligned, extending downspouts, installing splash blocks and building up the grade so that roof and surface water is diverted away from the building.

WINDOW WELLS

The amount of water, which enters a window well from falling rain, is generally slight, but water will accumulate in window wells if the yard is improperly graded. Plastic window well covers are useful in keeping out leaves and debris.

RETAINING WALLS

Retaining walls deteriorate because of excessive pressure buildup behind them, generally due to water accumulation. Excavating a trench behind the retaining wall and filling it with coarse gravel can often improve conditions. Drain holes through the wall will then be able to relieve the water pressure.

Retaining walls sometime suffer from tree root pressure or from general movement of topsoil down the slope. Normally, these conditions require rebuilding the retaining wall.

RAILINGS

It is recommended that railings be installed for any stairway over 3 steps and porches over 30" for safety reasons. Balusters for porches, balconies, and stairs should be close enough to assure children cannot squeeze through.



REMARKS

Valleys and Flashings that are covered with shingles and/or tar or any other material are considered not visible and are not part of the inspection.

Tar and Gravel Roofs are a type of covering on a pitched roof requires ongoing annual maintenance. We recommend that a roofing contractor evaluate this type of roof. Infra-red photography is best used to determine areas of potential leaks.

Flat roofs are very vulnerable to leaking. It is very important to maintain proper drainage to prevent the ponding of water. We recommend that a roofing contractor evaluate this type of roof.

ROOF TYPE	LIFE EXPECTANCY	SPECIAL REMARKS
<i>Asphalt Shingles</i>	15-20 years	Used on nearly 80% of all residential roofs; requires little maintenance
<i>Asphalt Multi-Thickness Shingles*</i>	20-30 years	Heavier and more expensive than regular asphalt shingles
<i>Asphalt Interlocking Shingles*</i>	15-25 years	Especially good in high-wind areas
<i>Asphalt Rolls</i>	10 years	Used on low slope roofs
<i>Built-up Roofing</i>	10-20 years	Used on low slope roofs; 2 to 3 times as costly as asphalt shingles
<i>Wood Shingles*</i>	10-40 years ¹	Treat with preservative every 5 years to prevent decay
<i>Clay Tiles*</i> <i>Cement Tiles*</i>	20 + years 20 + years	Durable, fireproof, but not watertight, requiring a good subsurface base
<i>Slate Shingles*</i>	30-75 years ²	Extremely durable, but brittle and expensive
<i>Asbestos Cement Shingles*</i>	30-75 years	Durable, but brittle and difficult to repair
<i>Metal Roofing</i>	15-40 + years	Comes in sheets & shingles; should be well grounded for protection from lightning; certain metals must be painted
<i>Single Membrane</i>	15-25 years (mfr's claim)	New material; not yet passed test of time
<i>Polyurethane with Elastomeric Coating</i>	5-10 years ¹	Used on low slope roofs.

* Not recommended for use on low slope roof

¹ Depending on local conditions and proper installation

² Depending on quality of slate

Roof coverings should be visually checked in the spring and fall for any visible missing shingles, damaged coverings or other defects. Before re-roofing, the underside of the roof structure and roof sheathing should be inspected to determine that the roof structure can support the additional weight of the shingles.

Wood shakes and shingles will vary in aging, due to the quality of the material, installation, maintenance, and surrounding shade trees. Ventilation and drying of the wood material is critical in extending the life expectancy of the wood. Commercial preservatives are available on the market, which could be applied to wood to impede deterioration.



REMARKS

CHIMNEYS

Chimneys built of masonry will eventually need tuck pointing. A cracked chimney top that allows water and carbonic acid to get behind the surface brick/stone will accelerate the deterioration. Moisture will also deteriorate the clay flue liner. Periodic chimney cleaning will keep you apprised of the chimney's condition. The flashing around the chimney may need resealing and should be inspected every year or two. Fireplace chimneys should be inspected and evaluated by a chimney professional before using. Chimneys must be adequate height for proper drafting. Spark arrestors are recommended for a wood burning chimney, and chimney caps for fossil fuels.

Unlined Chimney should be re-evaluated by a chimney technician.

Have flue cleaned and re-evaluated. The flue lining is covered with soot or creosote and representative samples were made as to the condition.

NOT EVALUATED

The flue was not evaluated due to inaccessibility such as roof pitch, cap, clean out, etc. If possible, evaluate.

CRICKET FLASHING

Small, sloped structure made of metal and designed to drain moisture away from a chimney. Usually placed at the back of a chimney.

GUTTERS AND DOWNSPOUTS

This is an extremely important element in basement dampness control. Keep gutters clean and downspout extensions in place (4' or more). Paint the inside of galvanized gutters, which will extend their life. Shortly after rain or thaw in winter, look for leaks at seams in the gutters. These can be recaulked but they cause damage to fascia or soffit boards. If no gutters exist, it is recommended that they be added.

SIDING

Wood siding should not come in contact with the ground. The moisture will cause rotting to take place and can attract carpenter ants. See page 34 for siding that have known problems, but are not always recognizable. EIFS This type of siding is a synthetic stucco and has experienced serious problems. It requires a certified EIFS inspector to determine condition.

Brick and stone veneer must be monitored for loose or missing mortar. Some brick and stone are susceptible to spalling. This can be caused when moisture is trapped and a freeze/thaw situation occurs. There are products on the market that can be used to seal out the moisture. This holds true for brick and stone chimneys also.

Metal siding will dent and scratch. Oxidation is a normal reaction in aluminum. There are good cleaners on the market and it is recommended that they be used occasionally. Metal siding can be painted.

DOORS AND WINDOWS

These can lose a tremendous amount of energy. Maintain the caulking around the frames on the exterior. Check for drafts in the winter and improve the worst offenders first. Windows that have leaky storm windows will usually have a lot of sweating. Likewise, well-sealed storms that sweat indicate a leaky window. It is the tighter unit that will sweat (unless the home has excess humidity to begin with).

Wood that exhibits blistering or peeling paint should be examined for possible moisture sources: roof leaks, bad gutters, interior moisture from baths or laundry or from a poorly vented crawl space. Some paint problems have no logical explanation, but many are a symptom of an underlying problem. A freshly painted house may mask these symptoms, but after you have lived in the home for a year or two, look for localized paint blistering (peeling). It may be a clue.

New glazing will last longer if the raw wood is treated with boiled linseed oil prior to glazing. It prevents the wood from drawing the moisture out of the new glazing.

CAULKING

Many different types of caulk are available on the market today. Check with a paint or hardware store for the kind of application you need.



REMARKS

EXTERIOR DOORS

The exposed side of exterior doors needs to be painted or properly stained and varnished to prevent discoloring and delamination. Weather-stripping is a must to prevent drafts.

ELECTRICAL

Extension cord wiring to an automatic door opener should be removed and the opener should install an outlet.

Sample



REMARKS

OVERHEAD DOOR OPENERS

We recommend that a separate electrical outlet be provided. Openers that do not have a **safety reverse** are considered a safety hazard. Small children and pets are especially vulnerable. We recommend the operating switches be set high enough so children cannot reach them. If a electric sensor is present, it should be tested occasionally to ensure it is working.

GARAGE SILL PLATES should be elevated or treated lumber should be used. If this is not the case, try to direct water away to prevent rotting.

A/C COMPRESSORS

They should not become overgrown with foliage. Clearance requirements vary, but 2' on all sides should be considered minimal with up to 6' of air discharge desirable. If a clothes dryer vent is within five to ten feet, either relocate the vent or do not run when the A/C is running. The lint will quickly reduce the efficiency of the A/C unit.

BURNERS

Any appliance such as a water heater, furnace, etc. should have the flame a minimum of 18" above the floor. Any open flame less than 18" from the floor is a potential safety hazard. The appliance should also be protected from vehicle damage.

Sample



KITCHEN REMARKS

PLASTER ON WOOD LATH

Plaster on wood lath is an old technique and is no longer in general use. Wood lath shrinks with time and the nails rust and loosen. As a result, the plaster may become fragile and caution is needed in working with this type of plastering system. Laminating drywall over the existing plaster and screwing it to the ceiling joists best repair sagging ceilings.

PLASTER ON GYPSUM LATH (ROCK LATH)

Plaster on gypsum lath will sometimes show the seams of the 16" wide gypsum lath but this does not indicate a structural fault. The scalloping appearance can be leveled with drywall joint compound and glass mesh joint tape or drywall can be laminated over the existing plaster on the ceiling.

WOOD FLOORING

Always attempt to clean wood floors first before making the decision to refinish the floor. Wax removers and other mild stripping agents plus a good waxing and buffing will usually produce satisfactory results. Mild buffing agents help remove deep stains. Sanding removes some of the wood in the floor and can usually be done only once or twice in the life of the floor.

NAIL POPS

Drywall nail pops are due to normal expansion and contraction of the wood members to which the drywall is nailed and are usually of no structural significance.

CARPETING

Where carpeting has been installed, the materials and condition of the floor underneath cannot be determined.

APPLIANCES

(If report indicated appliances were operated, the following appliances are tested. Dishwashers are tested to see if the motor operates and water sprays properly. Stoves are tested to see that burners are working and oven and broiler get hot. Timer and controls are not tested. Refrigerators are not tested.

No representation is made to continued life expectancy of any appliance.

ASBESTOS AND OTHER HAZARDS

Asbestos fibers in some form are present in many homes, but are often not visible and cannot be identified without testing.

If there is reason to suspect asbestos may be present and if it is of particular concern, a sample of the material in question may be removed and analyzed in a laboratory. However, detecting or inspecting for the presence or absence of asbestos is not a part of our inspection.

Also excluded from this inspection and report are the possible presence of, or danger from, radon gas, lead-based paint, urea formaldehyde, toxic or flammable chemicals and all other similar or potentially harmful substances and environmental hazards.

WINDOWS

A representative number of windows are inspected.



BATHROOM(S)

REMARKS

STALL SHOWER

The metal shower pan in a stall shower has a potential or probable life of 10-20 years depending on quality of the pan installed. Although a visible inspection is made to determine whether a shower pan is currently leaking, it cannot be stated with certainty that no defect is present or that one may not soon develop. Shower pan leaks often do not show except when the shower is in actual use.

CERAMIC TILE

Bathroom tile installed in a mortar bed is excellent. It is still necessary to keep the joint between the tile and the tub/shower caulked or sealed to prevent water spillage from leaking through and damaging the wallboard below. Ceramic tile is often installed in mastic. It is important to keep the tile caulked or water will seep behind the tile and cause deterioration in the wallboard. Special attention should be paid to the area around faucets and other tile penetrations.

EXHAUST FANS

Bathrooms with a shower should have exhaust fans when possible. This helps to remove excess moisture from the room, preventing damage to the ceiling and walls and wood finishes. The exhaust fan should not be vented into the attic. The proper way to vent the fan(s) is to the outside. Running the vent pipe horizontally and venting through a gable end or soffit is preferred. Running the vent pipe vertically through the roof may cause condensation to run down the vent pipe, rusting the fan and damaging the wallboard. Insulating the vent pipe in the attic will help to reduce this problem.

SLOW DRAINS on sinks, tubs, and showers are usually due to a build up of hair and soap scum. Most sink popups can be easily removed for cleaning. Some tubs have a spring attached to the rising lever which acts as a catch for hair. It may require removing a couple of screws to disassemble. If you cannot mechanically remove the obstruction, be kind to your pipes. **Don't use a caustic cleaner.** There are several bacteria drain cleaners available. They are available at hardware stores in areas where septic tanks are used. These drain cleaners take a little longer to work, but are safe for you and your pipes.

SAFETY HAZARDS

Typical safety hazards found in bathrooms are open grounds or reverse polarity by water. Replacing these outlets with G.F.C.I.'s is recommended.

WHIRLPOOL TUBS

This relates to interior tubs hooked up to interior plumbing. Where possible, the motor will be operated to see that the jets are working. Hot tub and spas are not inspected.



INTERIOR
ROOMS REMARKS

DOOR STOPS

All swinging doors should be checked for doorstops. Broken or missing doorstops can result in doorknobs breaking through drywall or plaster.

CLOSET GUIDES

Sliding closet doors should be checked to see that closet guides are in place. Missing or broken closet guides can cause scratches and damage to doors.

COLD AIR RETURNS

Bedrooms that do not have cold air returns in them should have a 3/4" gap under the doors to allow cold air to be drawn into the hall return.

AN INSPECTION VERSUS A WARRANTY

A home inspection is just what the name indicates, an inspection of a home, usually a home that is being purchased. The purpose of the inspection is to determine the condition of the various systems and structures of the home. While an inspection performed by a competent inspection company will determine the condition of the major components of the home, no inspection will pick up every minute latent defect. The inspector's ability to find all defects is limited by access to various parts of the property, lack of information about the property and many other factors. A good inspector will do his or her level best to determine the condition of the home and to report it accurately. The report that is issued is an opinion as to the condition of the home. This opinion is arrived at by the best technical methods available to the home inspection industry. It is still only an opinion.

A warranty is a policy sold to the buyer that warrants that specific items in the home are in sound condition and will remain in sound condition for a specified period of time. Typically, the warranty company never inspects the home. The warranty company uses actuarial tables to determine the expected life of the warranted items and charges the customer a fee for the warranty that will hopefully cover any projected loss and make a profit for the warranty seller. This is essentially an insurance policy.

The service that we have provided you is an inspection. We make no warranty of this property. If you desire warranty coverage, please see your real estate agent for details about any warranty plan to which their firm may have access.



REMARKS

WINDOW FRAMES AND SILLS

Window frames and sills are often found to have surface deterioration due to condensation that has run off the window and damaged the varnish. Usually this can be repaired with a solvent style refinisher and fine steel wool. This is sometimes a sign of excess humidity in the house.

See comments regarding caulking doors and windows.

FIREPLACES

It is important that a fireplace be cleaned on a routine basis to prevent the buildup of creosote in the flue, which can cause a chimney fire.

Masonry fireplace chimneys are normally required to have a terra cotta flue liner or 8 inches of masonry surrounding each flue in order to be considered safe and to conform with most building codes.

During visual inspections, it is not uncommon to be unable to detect the absence of a flue liner because of stoppage at the firebox, a defective damper or lack of access from the roof.

WOODBURNERS

Once installed, it can be difficult to determine proper clearances for wood burning stoves. Manufacturer specifications, which are not usually available to the inspector, determine the proper installation. We recommend you ask the owner for paperwork, verifying that a professional contractor installed it.

VENTILATION

Ventilation is recommended at the rate of one square foot of vent area to 100 square feet of attic floor space, this being divided between soffit and rooftop. Power vents should normally have both a humidistat and a thermostat, since ventilation is needed to remove winter moisture as well as summer heat. Presence of condensation such as blackened roof sheathing, frost on nail heads, etc. is an indication that ventilation may have been blocked or inadequate.

INSULATION

The recommended insulation in the attic area is R-38, approximately 12". If insulation is added, it is important that the ventilation is proper.

SMOKE DETECTORS

Smoke detectors should be tested monthly. At least one detector should be on each level. CO detectors are not required by most states, but for safety reasons, are highly recommended.

VAPOR BARRIERS

The vapor barrier should be on the warm side of the surface. Most older homes were built without vapor barriers. If the vapor barrier is towards the cold side of the surface, it should be sliced or removed. Most vapor barriers in the attic are covered by insulation and therefore, not visible.

SAFETY GLAZING

Safety glazing requirements vary depending on the age of the home. Every attempt is made to identify areas where the lack of safety glazing presents an immediate safety hazard, such as a shower door. In some older homes it is difficult to determine if safety glazing is present, since the glass is not marked. Therefore, no representation is made that safety glazing exists in all appropriate areas.

INSULATED GLASS

Broken seal in thermo pane/insulated windows are not always visible or detectible due to humidity and temperature changes during the day. Other factors such as window covering dirty windows, and lack of accessibility, personal property placed in front of the windows all effect the view of the windows at the time of the inspection.



REMARKS

BASEMENT

Any basement that has cracks or leaks is technically considered to have failed. Most block basements have step cracks in various areas. If little or no movement has occurred and the step cracks are uniform, this is considered acceptable. Horizontal cracks in the third or fourth block down indicate the block has moved due to outside pressure. They can be attributed to many factors such as improper grading, improperly functioning gutter and downspout system, etc. Normally if little or no movement has taken place and proper grading and downspouts exist, this is considered acceptable. If a crack containing the stress crack(s) has moved considerably, this will require some method of reinforcement. Basements that have been freshly painted or tuck pointed should be monitored for movement. This will be indicated by cracks reopening. If cracks reappear, reinforcement may be necessary. Reinforcing a basement wall can become expensive.

FOUNDATION (COVERED WALLS)

Although an effort has been made to note any major inflections or weaknesses, it is difficult to best to detect these areas when walls are finished off, or basement storage makes areas inaccessible. **No representation is made as to the condition of these walls.**

MONITOR indicates that the walls have stress cracks, but little movement has occurred. In our opinion, the cracks should be filled with mortar and the walls monitored for further movement and cracking. If additional movement or cracking occurs, reinforcement may be necessary.

HAVE EVALUATED We recommend that the walls be re-inspected by a structural engineer or basement repair company and estimates be obtained if work is required.

VAPOR BARRIER

Floors that are dirt or gravel should be covered with a vapor barrier.

MOISTURE PRESENT

Basement dampness is frequently noted in houses and in most cases the stains, moisture or efflorescence present is a symptom denoting that a problem exists outside the house. Usual causes are improper downspout extensions or leaking gutters and/or low or improper grade (including concrete surfaces) at the perimeter of the house. A proper slope away from the house is one inch per foot for four to six feet.

Expensive solutions to basement dampness are frequently offered. It is possible to spend thousands of dollars on solutions such as pumping out water that has already entered or pumping of chemical preparations into the ground around the house, when all that may be necessary are a few common sense solutions at the exterior perimeter. However, this is not intended to be an exhaustive list of possible solutions to the presence of moisture. **No representation is made to future moisture that may occur.**

PALMER VALVE

Many older homes have a valve in the floor drain. This drain needs to remain operational.

DRAIN TILE

We offer no opinion about the existence or condition of the drain tile, as it cannot be visibly inspected.

BASEMENT ELECTRICAL OUTLETS

We recommend that you have an outlet within 6' of each appliance. The appliance you plan to install may be different than what exists, therefore the inspection includes testing a representative number of receptacles that exist. It is also recommended to have ground fault circuit interrupts for any outlet in the unfinished part of the basement and crawl spaces.



REMARKS

CRAWL SPACES

Crawl spaces are shallow spaces between the first level floor joist and the ground. Access to this area may be from the inside, outside or not accessible at all. Ductwork, plumbing, and electrical may be installed in the space in which access may be necessary. The floor of the crawl space may be covered with concrete, gravel, or may be the original soil. A vapor barrier may be a sheet of plastic or tar paper and installed over or under this material. The vapor barrier will deter the moisture from the earth from escaping into the crawl space and causing a musty smell. Ventilation is also important to prevent excess moisture buildup. Vents may be located on the outside of the house and are normally kept open in the summer and closed for the winter (where freezing may occur).

The basement/crawl space diagram indicates areas that are covered and not part of a visual inspection. Every attempt is made to determine if paneling is warped, moisture stains are bleeding through, etc. Storage that blocks the view of a wall is not removed to examine that area. Therefore, it is important that on your walk-through before closing, you closely examine these areas.

Closed crawl spaces that have vents to the outside should have insulation under the floor above the crawl space.

HAVE EVALUATED

We recommend that the walls be re-evaluated by a structural engineer or foundation repair company and estimates be obtained if work is required.

MONITOR

Indicates that the walls have stress cracks, but little movement has occurred. In our opinion, the cracks should be filled with mortar and the walls monitored for further movement or cracking. If additional movement or cracking occurs, reinforcement may be necessary.

Sample



REMARKS

WELLS

Examination of wells is not included in this visual inspection. It is recommended that you have well water checked for purity by the local health authorities and, if possible, a check on the flow of the well in periods of drought. A well pit should have a locked cover on it to prevent anyone from falling into the pit.

SEPTIC SYSTEMS

The check of septic systems is not included in our visual inspection. You should have the local health authorities or other qualified experts check the condition of the septic system.

In order for the septic system to be checked, the house must have been occupied in the last 30 days.

WATER PIPES

Galvanized water pipes rust from the inside out and may have to be replaced within 20 to 30 years. This is usually done in two stages: horizontal piping in the basement first, and vertical pipes throughout the house next as needed. Copper pipes usually have more life expectancy and may last as long as 60 years before needing to be replaced.

HOSE BIBS

During the winter months it is necessary to make sure the outside faucets are winterized. This can be done by means of a valve located in the basement. Leave the outside faucets open to allow any water standing in the pipes to drain, preventing them from freezing. Hose bibs cannot be tested when winterized.

WATER HEATER

The life expectancy of a water heater is 5-10 years. Water heaters generally need to be replaced unless they leak. It is a good maintenance practice to drain 5-10 gallons from the heater several times a year. Missing relief valves or improper extension present a safety hazard.

WATER SOFTENERS

During a visual inspection it is not possible to determine if water is being properly softened.

PLUMBING

The temperature/pressure valve should be tested several times a year by lifting the valve's handle. Caution: very hot water will be discharged. If no water comes from the valve it is defective and must be replaced.

SHUT-OFF VALVES

Most shut-off valves have not been operated for long periods of time. We recommend operating each shut-off valve to: toilet bowl, water heater, under sinks, main shut-off, and faucets, and all others. We recommend you have a plumber do this, as some of the valves may need to be rechecked or replaced. Once the valves are in proper operating order, we recommend opening and closing these valves several times a year.

POLYBUTYLENE PIPING

This type of piping has a history of problems and should be examined by a licensed plumber and repaired or replaced as necessary.

MECHANICAL DEVICES MAY OPERATE AT ONE MOMENT AND LATER MALFUNCTION; THEREFORE, LIABILITY IS SPECIFICALLY LIMITED TO THOSE SITUATIONS WHERE IT CAN BE CONCLUSIVELY SHOWN THAT THE MECHANICAL DEVICE INSPECTED WAS INOPERABLE OR IN THE IMMEDIATE NEED OF REPAIR OR NOT PERFORMING THE FUNCTION FOR WHICH IS IT WAS INTENDED AT THE TIME OF INSPECTION.

CSST

Corrugated Stainless Steel Tubing is an alternative to traditional black iron gas piping. It is a continuous, flexible, stainless steel pipe with an exterior PVC covering.



HEATING SYSTEM

REMARKS

HEATING AND AIR CONDITIONING units have limited lives. Normal lives are:

GAS-FIRED HOT AIR.....	15-25 years
OIL-FIRED HOT AIR.....	20-30 years
CAST IRON BOILER.....	30-50 years
(Hot water or steam)	or more
STEEL BOILER.....	30-40 years
(Hot water or steam)	or more
COPPER BOILER.....	10-20 years
(Hot water or steam)	
CIRCULATING PUMP (Hot water).....	10-15 years
AIR CONDITIONING COMPRESSOR....	8-12 years
HEAT PUMP.....	8-12 years

Gas-fired hot air units that are close to or beyond their normal lives have the potential of becoming a source of carbon monoxide in the home. You may want to have such a unit checked every year or so to assure yourself that it is still intact. Of course a unit of such an age is a good candidate for replacement with one of the new, high efficiency furnaces. The fuel savings alone can be very attractive.

Boilers and their systems may require annual attention. If you are not familiar with your system, have a heating contractor come out in the fall to show you how to do the necessary thing **Caution: do not add water to a hot boiler!**

Forced air systems should have filters changed every 30 to 60 days of the heating and cooling season. This is especially true if you have central air conditioning. A dirty air system can lead to premature failure of your compressor - a \$1,500 machine.

A professional should service oil-fired furnaces and boilers each year. Most experts agree you will pay for the service cost in fuel saved by having a properly tuned burner.

Read the instructions for maintaining the humidifier on your furnace. A malfunctioning humidifier can rust out a furnace rather quickly. It is recommended that the humidifier be serviced at the same time as the furnace, and be cleaned regularly. **During a visual inspection it is not possible to determine if the humidifier is working.**

Have HVAC technician examine - A condition was found that suggests a heating contractor should do a further analysis. We suggest doing this before closing.

Heat exchangers cannot be examined nor their condition determined without being disassembled. Since this is not possible during a visual, non-technically exhaustive inspection, you may want to obtain a service contract on the unit or contact a furnace technician regarding a more thorough examination.

Testing pilot safety switch requires blowing out the pilot light. Checking safety limit controls requires disconnecting blower motor or using other means beyond the scope of this inspection. If the furnace has not been serviced in last 12 months you may want to have a furnace technician examine.

CO Test This is not part of a non-technical inspection. If a test was performed, the type of tester is indicated on the Heating System page.

Combustible Gas Detector If a gas detector was used during the inspection of the furnace and evidence of possible combustible gases was noted, we caution you that our test instrument is sensitive to many gases and not a foolproof test. None-the-less, this presents the possibility that a hazard exists and could indicate that the heat exchanger is, or will soon be, defective.




ELECTRIC/COOLING SYSTEM

REMARKS

Every effort has been made to evaluate the size of the service. Three wires going into the home indicate 240 volts. The total amperage can be difficult to determine. We highly recommend that ground fault interrupters (G.F.C.I.) be connected to all outlets around water. This device automatically shuts the circuit off when it senses a current leak to ground. This device can be purchased in most hardware stores. All outlets located near water; outside outlets, or garage outlets, recommend G.F.C.I.'s. Pool outlets should also be protected with a G.F.C.I.

See diagram below:



If you do have G.F.C.I.'s, it is recommended that you test (and reset) them monthly. When you push the test button, the reset button should pop out, shutting off the circuit. If it doesn't, the breaker is not working properly. If you don't test them once a month, the breakers have a tendency to stick and may not protect you when needed.

An electrician to insure that the wire cover is in good condition should check knob and tube wiring found in older homes. Under no circumstances should this wire be covered with insulation. Recess light fixtures should have a baffle around them so that they are not covered with insulation. The newer recessed fixtures will shut off if they overheat. (no representation is made as to proper recess lighting fixtures).

Federal Pacific Stab-Lok® Electrical panels may be unsafe.

See www.google.com (Federal Pacific)

Aluminum wiring in general lighting circuits has a history of over heating, with the potential of a fire. If this type of wiring exists, a licensed electrical contractor should examine the whole system.

ARC FAULTS

In some areas arc faults are required in new homes starting in 2002 and these control outlets in the bedrooms.

REVERSE POLARITY

A common problem that surfaces in many homes is reverse polarity. This is a potentially hazardous situation in which the hot and neutral wires on a circuit are reversed at the outlet, thereby allowing the appliance to incorrectly be connected. This is an inexpensive item to correct.

Each receptacle has a brass and silver screw. The black wire should be wired to the brass screw and the white wire should go to the silver screw. When the wires are switched, this is called "reverse polarity." Turning off the power and switching these wires will solve the problem.

Main service wiring for housing is typically 240 volts. The minimum capacity for newer homes is 100 amps though many older homes still have 60 amp service. Larger homes or all electric homes will likely have a 200-amp service.

One or more circuit breakers or fuses may protect Main service wiring. While most areas allow up to six main turnoffs, expanding from these panels is generally not allowed.

COOLING

Testing A/C System and Heat Pump- The circuit breakers to A/C should be on for a minimum of 24 hours and the outside temperature at least 60 degrees for the past 24 hours or an A/C system cannot be operated without possible damage to the compressor. Check the instructions in your A/C manual or on the outside compressor before starting up in the summer. Heat pump can only be tested in the mode it's running in. Outside temperature should be at least 65° for the past 24 hours to run in cooling mode.

Temperature differential, between 14°-22°, is usually acceptable. If out of this range, have an HVAC contractor examine it. It is not always feasible to do a differential test due to high humidity, low outside temperature, etc.

COSTS OF REMODELING OR REPAIR

The prices quoted below include a range of prices based on a typical metropolitan area. Individual prices from contractors can vary substantially from these ranges. We advise that several bids be obtained on any work exceeding \$500 dollars. **DO NOT RELY ON THESE PRICES... GET FURTHER ESTIMATES.**

ITEM	UNIT	ESTIMATED PRICE
Masonry fireplace	Each	\$4,000 - \$8,000
Install prefab fireplace	Each	2,000 - 4,000
Insulate attic	Square foot	.75 - 1.25
Install attic ventilating fan	Each	25 - 50
Install new drywall over plaster	Square foot	1.75 - 2.75
Install new warm air furnace	Each	1,800 - 3,500
Replace central air conditioning/heat pump	Per ton	1,000 - 1,500
Install humidifier	Each	100 - 500
Install electrostatic air cleaner	Each	800 - 1,500
Increase electrical service to 200 amps	Each	1,000 - 1,500
Run separate elec. line for dryer	Each	125 - 200
Run separate elec. line for A/C	Each	100 - 200
Install hardwired smoke detector	Each	100 - 180
Install new disposal	Each	150 - 250
Install new dishwasher	Each	500 - 1,000
Install new hot water boiler	Each	2,000 - 4,000
Install new 30-50 gallon water heater	Each	350 - 650
Install new 75 gallon water heater	Each	750 - 1,000
Dig and install new well	Each	get estimate
Install new septic system	Each	get estimate
Re-grade around exterior	Each	get estimate
Install new sump pump	Each	150 - 300
Build new redwood or pressure-treated deck	Square foot	15 - 30
Install storm windows	Each	60 - 150
Install wood replacement windows	Each	400 - 800
Install aluminum or vinyl replacement window	Each	150 - 400
Install new gutters and downspouts	Lineal foot	4.00 - 8.00
Install asphalt shingle on existing roof	Square foot	1.20 - 1.70
Tear off existing roof and install new asphalt shingle roof	Square foot	2.50 - 4.00
Install 1-ply rubberized roof	Square foot	get estimate
Install 1-ply built-up tar & gravel	Square foot	get estimate
Remove asbestos from pipes in basement	Lineal foot	get estimate
Concrete drive or patio	Square foot	4.50 - 9.00
Plus removal of old concrete	Square foot	1.50 - 3.00
Clean chimney	Each	100 - 200
Add flue liner for gas fuel	Each	900 - 1,200
Add flue liner for oil or wood	Each	2,800 - 3,500

Deferred Costs - It is impossible to determine how long these items will last before needing replacement. The report addresses most of these items from a "condition" standpoint.

PREVENTIVE MAINTENANCE TIPS

- I. **FOUNDATION & MASONRY: Basements, Exterior Walls:** To prevent seepage and condensation problems.
 - a. Check basement for dampness & leakage after wet weather.
 - b. Check chimneys, deteriorated chimney caps, loose and missing mortar.
 - c. Maintain grading sloped away from foundation walls.

- II. **ROOFS & GUTTERS:** To prevent roof leaks, condensation, seepage and decay problems.
 - a. Check for damaged, loose or missing shingles, blisters.
 - b. Clean gutters, leaders, strainers, window wells, drains. Be sure downspouts direct water away from foundation. Cut back tree limbs.
 - c. Check flashings around roof stacks, vents, skylights, and chimneys, as sources of leakage. Check vents, louvers and chimneys for birds nests, squirrels, insects.
 - d. Check fascias and soffits for paint flaking, leakage & decay.

- III. **EXTERIOR WALLS:** To prevent paint failure, decay and moisture penetration problems.
 - a. Check painted surface for paint flaking or paint failure. Cut back shrubs.
 - b. Check exterior masonry walls for cracks, looseness, missing or broken mortar.

- IV. **DOORS AND WINDOWS:** To prevent air and weather penetration problems.
 - a. Check caulking for decay around doors, windows, corner boards, joints. Re-caulk and weather-strip as needed. Check glazing, putty around windows.

- V. **ELECTRICAL:** For safe electrical performance, mark & label each circuit.
 - a. Trip circuit breakers every six months and ground circuit interrupters (G.F.C.I.) monthly.
 - b. Check condition of lamp cords, extension cords & plugs. Replace at first sign of wear & damage.
 - c. Check exposed wiring & cable for wear or damage.
 - d. If you experience slight tingling shock from plugging or touching any appliance, disconnect the appliance & have it repaired. If lights flicker or dim or if appliances go on and off unnecessarily, call a licensed electrician.

- VI. **PLUMBING:** For preventive maintenance.
 - a. Drain exterior water lines, hose bibs, sprinklers, pool equipment in the fall.
 - b. Draw off sediment in water heaters monthly or per manufacturer's instructions.
 - c. Have septic tank cleaned every 3 years.

- VII. **HEATING & COOLING:** For comfort, efficiency, energy conservation and safety.
 - a. Change or clean furnace filters, air filtration filters, electronic filters as needed.
 - b. Clean and service humidifier. Check periodically and annually.
 - c. Have oil burning equipment serviced annually.

- VIII. **General home maintenance.**
 - a. Check bathroom tile joints, tub grouting & caulking. Be sure all tile joints in bathrooms are kept well sealed with tile grout to prevent damage to walls, floors & ceilings below.
 - b. Close crawl vents in winter and open in summer.
 - c. Check underside of roof for water stains, leaks, dampness & condensation, particularly in attics and around chimneys.

- IX. **Know the location of:**
 - Main water shutoff valve.
 - Main electrical disconnect or breaker.
 - Main emergency shutoff switch for the heating system.